

## OPEL Mobile Phone Portals

Certified according to the Bluetooth- Standard (Handsfree Profile 1.5) and compatible with a multitude of bluetooth capable cell phones.

Due to a variety of available cell phones, however, the compatibility with all models cannot be ensured.

Please find below a current overview of compatible phone models.

Supported Phones	Cradle	Cradle part number	Phone software	Bluetooth Connection	Comments / Deviations
<b>Siemens / BenQ</b>					
Siemens C/S/M 55	yes	93 199 054	C55: V 24; S55: V 91; M55: V 91	only S55	Bluetooth pairing has to be done from mobile phone
Siemens C65	yes	93 199 065	V 25	no	
Siemens CX/M65, CX70	yes	93 199 052	CX65: V 16; M65: V 25; VX70: V 34	no	
Siemens S/SP 65	yes	93 199 055	S65: V43; SP65: V47	yes	
Siemens S75	yes	93 199 363	SW 38 , 29.12.2005	yes	Unsteable Bluetooth connection with some software versions
Siemens CX75	yes	93 199 333	SW 13 , 09.01.2006	yes	
Siemens C75	yes	93 199 381	SW 22 , 19.11.2005	no	
Siemens M75	yes	93 199 334	SW 23 , 10.05.2005	yes	
<b>Nokia</b>					
Nokia 3100	yes	93 199 060	V 05.02	no	
Nokia 6020/6021	yes	93 199 332	N6020: V 03.52; N6021: V 03.83	yes	
Nokia 6100	yes	93 199 061	V 05.51	no	
Nokia 6220	yes	93 199 062	V 5.15	yes	
Nokia 6230/6230i	yes	93 199 058	N6230: V 05.50; N6230i: V 03.40	yes	Limited display functions over Bluetooth
Nokia 6310/6310i	yes	93 199 354	N6310: V 05.01; N6310i: V 07.00	yes	Limited display functions over Bluetooth
Nokia 6610/7210/7250/7250i	yes	93 199 063	N6610: V 05.52; N7210: V 04.74; N7250: V 03.62; N7250i: V 05.30	yes	Nokia 6610i is not released for cradle mode since the performance of the antenna coupling is not sufficient. Limited display functions over Bluetooth
Nokia 6820	yes	93 199 059	V 04.25	yes	Nokia 6822 has not been released since the antenna coupler performance was rated as insufficient. Limited display functions over Bluetooth
<b>Sony Ericsson</b>					
Sony Ericsson T610/630	yes	93 199 057	T610: V R6C005; T630: V R7A011	yes	Long transmission time for phone book entries
Sony Ericsson K700i	yes	93 199 056	V R2AE033	yes	Partly no or incomplete transmission of phone book entries both in cradle mode as well as in Bluetooth mode.
<b>Motorola</b>					
Motorola V635/620/600/550/52	yes	93 199 053	V635: V R474_G_08.48.24R_A; V620: V R376_G_0E.65.25R; V600: V TRIPLETS_G_OB.09.38R_V; V550: V R367_G_0E.65.14R_A; V525: V TRIPLETS_G_OB.09.38R_V; V500: V TRIPLETS_G_OB.09.38R; V400: V TRIPLETS_G_OB.08.AAR_A; V300: V TRIPLETS_G_OB.09.37R		

Note: Function deviation in cradle mode are described in the manual of the cradle